MBF465/

FOCUSED ENVIRONMENTAL ASSESSMENT OF THE INTEGRATED SPECIALTIES, INC. SITE

Prepared for

McLachlan Investment Company 1400 Dove Street Newport Beach, CA 92660

Prepared by

BCL Associates, Inc. 5702 Bolsa Avenue Huntington Beach, CA 92649 (714) 892-2565

BCLA Project Number 88-524

August 1988

The information contained in this report has received appropriate technical review and approval. The conclusions and recommendations presented represent professional judgements and are based upon the findings from the investigation identified in the report and the interpretation of such data based on our experience and background. This acknowledgement is made in lieu of all warranties, either expressed or implied.

Project Manager

J. Severns James'

Certified Hazardous Materials Manager - No. 372 Certified Hazard Control Manager - No. 1885 Certified Safety Executive - No. 658 California Registered Environmental Assessor

Reviewed and Approved By

Robert L. Litzenberg, California Registered Civil Engineer

No. 31245

6.229.PRT-T11

#### TABLE OF CONTENTS

Section		Page
1.0	INTRODUCTION 1.1 Project Objectives 1.2 Project Location 1.3 Background	1 1 1
2.0	FIELD INVESTIGATION	3
3.0	CHEMICAL ANALYSIS	9
4.0	FINDINGS AND RECOMMENDATIONS	10
	TABLES	
Number		Page
1 2 3 4 5	Sample Identification and Field Analytical Readings TTLC Analysis TTLC Concentrations Which Equal or Exceed STLC Values STLC Analysis Sample pH Levels Volatile Organic Compounds	6 11 12 13 14 15
	FIGURES	
Number		Page
1 2	Site Location Map Boring Locations	2 5
	APPENDICES	
A B C D	Engineer's Report on Groundwater Conditions Boring Logs Laboratory Analytical Reports California Site Mitigation Decision Tree Manual: RSCL's	

6.229.RPT-TC

3

#### 1.0 INTRODUCTION

#### 1.1 Project Objectives

The objective of this project was to provide an indication of whether significant levels of chemical contamination exist in the soils underlying the Integrated Specialties, Inc. site. This evaluation was based upon the analysis of soil samples collected from areas of concern previously identified at the subject site.

#### 1.2 Project Location and Surrounding Land Use

The Integrated Specialties, Inc. site is located at 1551 East Orangethorpe in Fullerton, California. Figure 1 shows the location. The 116,000 square foot Integrated Specialties, Inc. building is located in a manufacturing center. The surrounding land use is manufacturing and office space.

#### I.3 Background

Ð,

On October 22, 1986, BCLA performed an inspection of the Integrated Specialties, Inc. site. Integrated Specialties is a division of Allegheny International. Mr. Don Farmer of Integrated Specialties, Inc. and Mr. David Mitchell of McLachlan Investment Company accompanied BCLA on the inspection.

Based upon a review of the Engineer's Report on Groundwater Conditions, the groundwater level at the site location was determined to be 50 to 70 feet below ground surface. See Appendix A for the Groundwater Contour Maps consulted.


At the time of the inspection the plant was inactive. Virtually all of the process equipment had been removed from the facility. Mr. Farmer reported that the equipment had been previously sold at an auction. Mr. Farmer's crew was in the process of cleaning the interior of the building. It was reported that Integrated Specialties was responsible for cleaning the entire facility prior to leaving the site.

Mr. Farmer reported that Integrated Specialties, Inc. had been on the site since 1956. Prior to that, Ensign Carburator operated a carburator repair and rebuilding operation on the site. Mr. Farmer indicated that the Integrated Specialties, Inc. lot has been paved since 1956.

Mr. Farmer stated that Integrated Specialties, Inc. did chemical milling, etching and plating of steel parts using ferric chloride. It was reported that as part of this operation industrial wastewater containing iron, nickel and copper was generated and discharged to the industrial sewer lines. Mr. Farmer reported that during their entire operating period, Integrated Specialties, Inc. received only one notice of violation from the local Sanitation District. That violation was related to excessive nickel in the wastewater.

At the time of the 1986 inspection, the plant had 5 industrial wastewater clarifiers, 2 outside the building on the east side, 1 in the etch room, 1 in the drag-out room and 1 near the 1,1,1-Trichloroethane degreasing tank near the center of the building. There is one common sampling point downstream of the clarifiers near the northeast corner of the building. The industrial sewer for the facility runs in a north to south direction under the parking lot on the east side of the building.

-1-



At the time of BCLA's 1986 inspection, the filter press area and above ground raw chemical storage tank area near the northeast corner of the property had reddish-brown staining on the surface of the pavement. The staining was reported by Mr. Farmer to be residual ferric chloride. Some brown staining was also observed around the stormwater catch basin near the filter press.

As part of the cleaning, etching, plating and milling operation parts were exposed to hydrochloric and nitric acids, sodium hydroxide and ferric chloride. These operations primarily occurred on the east side of the building. The operations occurred on a bermed concrete slab with a raised wooden grate floor. The concrete slab had a layer of reddish-brown powder at the time of the inspection. Some corrosion of the concrete was observed. Mr. Farmer reported that the pH of the liquids used in these areas was kept between 7-1/2 and 8. Mr. Farmer also said that the concrete slabs would be thoroughly cleaned prior to Integrated Specialties leaving the site.

The facility had two l,l,l-Trichloroethane cleaning tanks, one at the north end and one near the center of the building. The cleaning fluids were held in steel tanks set in concrete sumps. Any fluids which leaked from the steel tank would drain into the sump. Mr. Farmer indicated that he was not aware of any l,l,l-Trichloroethane leaks, although on occasion water from nearby processes had overflowed into the sumps. Visual inspection of the concrete sumps did not identify any obvious leak points in the sump walls.

Outside the building on the west side was an eight foot deep concrete sump for a previously removed cooling water system. Mr. Farmer indicated that Phosglass 504, which is manufactured by Water Chemists, Inc. in Los Angeles, was added to the water to prevent the growth of algae and control scale.

Three large transformers mounted on a concrete slab were observed near the northwest corner of the building. Mr. Farmer reported that these transformers were owned and maintained by the local electrical utility. No evidence of leakage was noted around the transformers.

This inspection was incorporated in a Preliminary Environmental Audit prepared for the facility in 1986 by BCLA.

#### 2.0 FIELD INVESTIGATION

The Preliminary Audit identified areas of potential environmental liability based on file searches and on one site inspection. No documented areas of soil contamination were identified during the preliminary audit process. However, the following five areas were identified as having a potential for soil contamination were identified:

- ° Industrial Wastewater Clarifiers
- ° 1,1,1-Trichloroethane Tanks
- ° Cooling Water Sump
- Bermed Concrete Pad
- ° Electrical Transformer Pad

Ŧ3

3

On January 25 and 26, 1988, BCL Associates, Inc. (BCLA) conducted a soils investigation at the site formerly occupied by Integrated Specialties, Inc. focused on the areas of concern. Soil samples were collected from 15 hand auger borings, in addition to 2 surface grab samples. A total of 57 samples were collected. Figure 2 shows the boring and grab sample locations. In addition to these areas, a surface grab sample was obtained from soil accumulated in a ditch which transports runoff water from the east side of the property to a storm drain inlet.

The samples were visually inspected and logged in the field by a qualified geologist. The samples were also screened by field instruments using the headspace method. The instruments used for this screening were a portable flame ionization detector (FID) and photo ionization detector (PID). Total petroleum hydrocarbons (TPH) were determined by analyzing samples with a Miran Infrared Spectrometer (IR) using the modified EPA method 418.1. Appendix B includes copies of the boring logs which list the lithologic descriptions, as well as field PID, FID and IR readings.

Table 1 shows the Areas of Concern; Boring Numbers within these areas; Sample Numbers; Depth of Sample Collection; PID, FID and IR Readings; and Initial Laboratory Analysis requested adjacent to the samples analyzed.

A hand auger was used to collect the soil samples from the boring locations. Considerable difficulty maintaining an open borehole was encountered in several of the borings. The site is underlain predominantly by sand. This sand has poor cohesive properties. The boreholes therefore exhibited a tendency to collapse during sampling operations.

The samples were collected in stainless steel sleeves and in 250 ml glass jars. The sleeve samples were immediately sealed and labeled upon collection. The samples were then transferred to an insulated chest, cooled with dry ice and delivered to the selected laboratory the same day. The portion of the sample collected in the 250 ml glass jar was subjected to field headspace analysis using a PID and FID. A portion of each sample was analyzed in the field for TPH using the IR.

A description of the field activities undertaken at each area of concern is given below. See Figure 2 for boring locations.

#### Industrial Wastewater Clarifiers

A total of 4 shallow borings (B-I through B-4) were drilled at these locations. The subsurface soils were visually clean and consisted of olive-brown silty sand. Field headspace analysis readings of the samples from these borings using the PID did not exceed 30 ppm. The FID readings did not exceed 80 ppm. Field IR analysis results for TPH did not exceed 93 ppm.

ۇي

()

53

. . 4

# TABLE 1 Sample Identification and Field Analytical Readings

AREA OF CONCERN	BORING NUMBER	SAMPLE NUMBER	DEPTH*	FIELD READING			LABORATORY ANALYS IS REQUESTED
Clarifier	B-1	1 2 3	5 18 30	5 15 9	25 30 30	24 7 14	17 TILC, pH
Containment Area	B-2	4 5 6 13	6 18 30 42	8 24 20 19	25 80 48 12	7 14 14 7	17 TYLC.pH
Containment Area	B-3	7 8 9 14	6 18 30 42	20 18 24 15	28 24 28 20	21 <7 <7 <7	17 TTLC, pH
Clarifier	B-4	10 11 12 15	10 22 32 45	30 30 22 6	50 60 32 19	93 7 <7 7	17 TTLC,pH
Bermed Concrete Pad	<b>B-</b> 5	16 17 18	8 20 32	13 16 23	200 190 80	57 14 7	17 TTLC, pH
	B-7	22 23 24	6 18 30	12 32 62	22 75 70	<7 <7 <7	17 TTLC,pH
	B-8	25 26 27 57	5 17 29 41	12 16 28 120	40 60 30 200	7 7 445 <7	17 TTLC,PH  VOA (8240)
	B-9	28 29 30	4 16 28	24 58 32	50 30 100	<7 <7 <7	17 TTLC,pH
	B-10	31 32 33	4 16 28	25 12 40	80 40 80	7 <7 <7	17 TTLC,pH
	B-11	34 35 36	12 24 36	25 30 60	40 80 150	<7 <7 7	17 TTLC,pH
	B- 12	37 38 39	12 24 36	15 20 30	40 60 80	<7 <7 <7	17 TTLC,pH

..2

3)

TABLE 1
Sample Identification
and Field Analytical Readings

AREA OF CONCERN	BORING NUMBER	SAMPLE NUMBER	DEFTH*		ANALYT GS (in FID		LABORATORY ANALYS IS REQUESTED
1,1,1-Trichloro- ethane tanks	B-6	19 20 21	6 18 30	142 154 15	280 190 70	150 143 71	VOA (8240)
	B-13	40 41 42	6 18 30	15 35 30	30 70 50	14 85 14	VOA (8240)
Cooling Water Sump	B-14	43 44 45 46 47 48 49 50	4 1 ft 2 ft 3 ft 4 ft 5 ft 6 ft 7 ft	90 110 100 25 15 20	2000 70 150 70 20 20 15 25	735 <7 14 <7 <7 14 <7 <7 <7 <7	17 TTLC, pH VOA (8240)
Electric Transformer Pad	B-15	51 53 54 55	8 ft 0 12 24	10 5 5	60  15 12 12	<7 110 14 <7	PCB (8080)
	Grab Sample	52	0	1	20	1270	PCB (8080)
Run-off Ditch	Grab Sample	56	0	5	12	2230	

\* - Depth in inches unless otherwise indicated

#### 1, 1, 1-Trichloroethane Tanks

#### Northern Tank (Concrete Pit)

Boring B-6 was advanced to a total depth of 30 inches below the concrete pit. The bottom of the pit is about 3 feet below ground surface. The concrete floor of the pit is 6 inches thick and in good condition with no apparent cracks.

Soils below the concrete pad consist mostly of silty clayey sand and fine sand, olive-brown in color. No visible staining was observed in the collected soils.

High PID, FID and IR readings were detected in this boring. Sample number 19, which was collected directly below the concrete slab at 6 inches below ground surface (BGS) showed field instrument readings of 142 ppm on the PID, 280 ppm on the FID and 150 ppm of TPH on the IR.

#### Center Tank (Concrete Pit)

زی

4

۲.

:

1.

è

One soil boring (B-13) was drilled at this location to a total depth of 31 inches below the top of the concrete floor of the pit. Soil samples were collected directly below the concrete slab and at approximately 12-inch intervals thereafter. The concrete floor in the pit was 12 inches thick and in good condition with no appartent cracks.

Soils below the concrete slab at this location consist of fine to coarse loose sand, olive-brown to pale yellow in color. This sand probably was imported as fill material during construction of the concrete pit. No visible staining was observed.

Peak field instrument readings for this area were 35 ppm on the PID, 70 ppm of the FID and 85 ppm on the IR.

## Cooling Water Sump

One soil boring (B-14) was placed at this location to a depth of 8 feet below ground surface. Soil samples were collected immediately below the concrete slab and at 1-foot intervals thereafter. The concrete slab was in good condition with no evidence of cracking or corrosion.

Soils below the concrete slab predominatly consisted of olive-brown silty sand. No visible contamination or soil discoloration was observed at the boring location.

Sample number 43 was collected at 4 inches below the top of the concrete slab. This sample exhibited field instrument readings of 600 ppm (PID), 2000 ppm (FID) and 785 ppm TPH (IR). The balance of the samples from this boring showed considerably lower readings for the remainder of the samples from this boring did not exceed 110 ppm (PID), 150 ppm (FID) and 14 ppm TPH.

#### Bermed Concrete Pad

Within this area, 7 borings (B-5 and B-7 through B-12) were placed. The underlying soils were comprised of silty-clayey plive sand of varying grades from fine to medium.

The concrete slab in this area varied from 3 to 8 inches in thickness. The surficial concrete was corroded in the areas of borings 5, 8, 9, 10, 11 and 12. No cracks in the concrete were observed.

PID readings in this area were below 60 ppm, except in sample number 57, which had a PID level at 120 ppm. This sample also had the highest FID level in this area, being 200 ppm. TPH levels did not exceed 57 ppm, except in sample number 27 which had a level of 445 ppm. Both of these samples were obtained from boring B-8, which could not be advanced deeper due to extensive caving of the surrounding sand.

#### Runoff Ditch

.

This ditch collects water runoff from the parking areas along the east side of the building. Sample number 56 was obtained from accumulated soil in the ditch near the Storm Drain Inlet situated near the northeast end of the property. The PID reading for Sample Number 56 was 5 ppm, the FID reading was 12 ppm. The TPH level was 2230 ppm.

### Electrical Transformer Pad

One surface grab sample (sample number 52) was collected from oil stained sandy soil that had accumulated on the surface of the Electrical Transformer Pad. This sample exhibited PID readings of 1 ppm, FID readings of 20 ppm and TPH concentration of 1270 ppm.

Boring B-15 was placed in an area where possible leakage from the Electrical Transformers would have come in contact with the soil. This area was selected by pouring a small amount of clean water on the pad at the point where the transformer was mounted. The sample collection point was defined at the point where the water reached the soil. Presumably, any liquid released by a transformer could follow the same path. Surficial soils at the boring location and around the pad did not exhibit any visible evidence of staining. Soils from the boring were olive-brown silty sand, with no visible staining. Field instrument readings from this boring did not exceed 10 ppm (PID), 15 ppm (FID) and 110 ppm TPH.

#### 3.0 CHEMICAL ANALYSIS

Samples were selected for analysis based on review of the boring logs. Table 1 shows the borings segregated by area of concern, the samples collected at each boring, the depth of sample collection below ground surface, field instrument readings and the preliminary laboratory analyses performed on the selected samples.

Appendix C contains copies of the laboratory analytical reports.

-9-

6.229, RPT-5

#### Metals Analysis

Table 2 shows the results of the Total Threshold Limit Concentration (TTLC) analyses. None of the samples analyzed exceeded the TTLC values in Title 22, Division 4, Chapter 30, Article 11 (Title 22), Section 66699.

Table 3 focuses on those samples whose TTLC concentration equaled or exceeded Section 66699 STLC values. These samples were analyzed for soluble metals by the Waste Extraction Test (WET) in accordance with Section 66700. Table 4 shows the result of these analyses. None of the samples analyzed for soluble metals exceeded the Soluble Threshold Limit (STLC) values.

#### pH Determination

2

3 . . Table 5 shows the pH levels of the samples selected for analysis. Refer to Table 1 for sample depth and boring position. Sample 7 from Boring B-3 had the highest pH (11.4) of all the samples analyzed. This is below the corrosivity hazard determination of 12.5 set forth in Title 22 §66708.

#### Volatile Organic Analysis

Table 6 shows the Volatile Organic compound concentrations found in the analyzed soil samples in conjunction with the Drinking Water Standards and the Recommended Soil Cleanup Levels (RSCL's), discussed below.

#### Polychlorinated Biphenyls (PCB's)

Two samples from the Electrical Transformer Pad area were analyzed for PCB's by EPA method 8080. PCB's were found in both samples.

Sample	PCB Concentration	Location
52	4.4 ppm	Surface of Transformer Pad
53	0.22 ppm	Boring B-15-Groundsurface

## 4.0 FINDINGS AND RECOMMENDATIONS

TTLC metals analysis of selected samples and subsequent focused STLC analysis revealed no TTLC or STLC limit exceedances in any samples analyzed from the site. The pH levels are within the values published in Title 22, Section 66708.

Volatile Organic Compounds (VOC's) were found in the samples 19, 41, 43 and 57. These samples were judged to represent the highest probability of containing VOC's, based upon the review of the field instrument readings. Table 6 shows the VOC concentrations found in the soil juxtaposed with the accepted Drinking Water Standards and the Recommended Soil Cleanup Levels (RSCL) derived by formula provided in the Appendix of the California Site Mitigation Decision Tree Manual (May 1986, Section VIII: California Soil.

MIC000061

TABLE 2 TTLC Analysis

15 To 16 To

								SAMPLE	NUKBER					
COMPOUND	STLC	TTLC	1	4	7	10	16	22	25	28	31	34	<b>3</b> 7	43
Antimony	15	500	ND:0.6	ND:0.6	ND:0.6	ND(0.6	ND(0.6	ND(0.6	ND<0.6	ND<0.6	8.0 ADK	ND(0.6	ND+0.6	ND(0.6
Arsenic	5.0	500	2.7	1.9	4.6	6.3	8.3	2.9	4.0	2.7	4.7	2.5	3.0	7.1
Barium	100	10000	64	93	53	56	88	70	110	104	92	53	102	83
Beryllium	0.75	75	0.25	0.42	0.32	0.35	0.39	0.35	0.47	0.48	0.43	1.2	0.47	0.40
	1.0	100	0.47	0.56	ND(0.1	ND∢0.1	0.21	ND(0.1	0.57	0.17	0.19	ND < 0.1	0.31	0.87
Cadmium	560	2500	14	21	45	16	22	20	36	27	24	29	27	79
Chromium, total		8000	4.3	19	12	5.4	35	5.8	7.4	22	9.2	15	7.2	6.5
Cobalt	80	2500	4.₃ 6.1	16	42	9.2	38	8.1	14	13	11	50	12	12
Copper	25		2.6	3.2	8.1	27	29	2.5	8.7	7.6	16.7	33	9.1	42
lead	5.0	1000	2.0 ND(0.09	3.2 ND:0.09	ND(0.09	ND: 0.09	ND: 0.09	ND(0.09	HD(0.09	ND(0.6	ND+0.6	ND (0.6	ND(0.6	ND(0.6
Kercury	0.2	20		2.5	4.6	1.3	2.6	1.9	3.3	2.4	2,2	2.1	2.7	2.5
Molybdenum	350	3500	1.6		150	11	120	13	22	18	15	220	17	15
Nickel	20	2000	12	320		ND(0.6	ND(0.6	ND:0.6	ND(0.6	ND(D.6	ND(0.6	ND+0.5	ND(0.6	ND(0.6
Selenium	1.0	100	NDcG.6	ND<0.6	ND(0.6	-	12	11	16	17	15	17	17	13
Silver	5	500	9.4	14	9.9	10		NDc0.6	ND: 0.6	ND(0.6	ND(0.6	ND(0.6	ND∢0.6	ND(O.6
Thallium	7.0	700	ND<0.6	ND<0.6	MD:0.6	ND(0.6	HD(0.6	44	69	67	58	55	69	52
Vanadium	24	2400	38	53	56	44	50	• •		59	54	160	60	160
Zinc	250	5000	24	60	69	43	68	44	60	23	74	100	00	,

4 1 4 4

ND - none detected [All units shown in parts per million (ppm)]

TABLE 3
TTLC Concentrations
Which Equal or Exceed STLC Values

The Control of the Co

					<del></del>			SAHPLE	NUHBER					
COMPOUND	TTLC	STLC	1	4	7	10	16	22	25	28	31	34	37	43
	500	15												
Antimony		5.0				6.3	8.3							7.1
Arsenic	500								110	104			102	
Barium	10000	100										1.2		
Beryllium -	75	0.75												
Cadmium	100	1.0	<del></del>											
Chromium, total	2500	560												
Cobalt	8000	80										50		
Copper	2500	25			42		38			7.6	16.7	. 33	9.1	42
Lead	1000	5.0			8.1	27	29		8.7			. 33		
Mercury	20	0.2												
Holybdenum	3500	350												
Nickel	2000	20		320	150		120		22			220		
	100	1.0												
Selenium		5	9.4	14	9.9	10	12	11	16	17	15	17	17	13
Silver	500	-	7.4											
Thallium	700	7.0			56	44	50	44	69	67	58	<b>\$</b> 5	69	52
Vanadium	2400	24	38	53										
Zinc	5000	250												

---- = STLC not exceeded
All units shown in parts per million (ppm)

TABLE 4 STLC Analysis

. Jan 1922

			STLC Detection						SAMPLE	NUMBER					
COMPOUND	TTLC (mg/Kg)		Limit (mg/L)	1	4	7	10	16	22	25	28	31	34	37	43
Antimony	500	15													
Arsenic	500	5.0	0.03	•			0.28.	0.15							0.16
Barium	10000	100	0.02							5.3	5.2			5.3	
Beryllium	75	0.75	0.02										0.05		
	100	1.0	V.02												
Cadmium	2500	560													
Chromium, total	8000	80					<b>-</b>	~							
Cobalt		25	0.01			0.69		3.3					2.5		
Copper	2500		0.01			TR	2.0	1.1		TR	TR	TR	1.1	TR	1.7
Lead	1000	5.0	0.2												
Mercury	20	0.2													
Kolybdenuæ	3500	350	2.00			2.4		7.0		0.51			12		
Nickel	2000	20	0.08		8.8			7.0							
Seleniu <b>≥</b>	100	1.0				2		HD	ND	0.2	ND	ИD	ND	ND	HD
Silver	500	5	0.02	HD	ND	0.4	0.3		+						
<b>Thallium</b>	700	7.0						NO.	ND	МD	ND	ND	מא	MD	ND
Vanadiu <b>n</b>	2400	24	0.04	ND	HD	ND	ND	DN		110	710				
Zinc	5000	250													

ND - None detected

TR - Trace, below detection limit
---- = STLC analysis not required
All units shown in parts per million (ppm)

TABLE 5 Sample pH Levels

SAMPLE NUMBER	PH LEVELS
	9.4
1	
4	10.2
7	11.4
10	9.2
16	8.7
22	10.1
25	8.6
28	8.1
31	8.0
34	9.6
37	9.1

77

3

# TABLE 6 Volatile Organic Compounds

	DRINKI	NG WATER	STANDARDS		SAMPLE NUMBER					
COMPOUND	EPA	EPA	CADHS	RSCL	19	41	43	57		
CONTROLL	HCL	RMCL	Act, Level							
Methylene Chloride			40	40,000	70		280	86		
Acetone					19					
2-Butanone					21		.,	••		
2-Hexanone					14					
Tetrachloroethene			4	4,000	7		31	27		
Vinyl Acetate						37	• •	• •		
1.1.1-Trichloroethane		200	200	200,000	(0.9	••	• •	5		
Trichloroethene					٤2.		••	13		
1.2-Dichloroethane			1.0	1,000	(0.5	, .	• •	• •		
Carbon Tetrachloride			5.0	4,000	(0.4	••	• •			
Bromodichloromethane	100				(0.4		•••	••		
Benzene			0.7	700	€ 2.		••	• •		
4-Methyl-2-Pentanone					( 9.		* 1	• •		
Chlorobenzene					∢0.6		• •	• •		
Ethylbenzene					€0.9		••	• •		
Styrene					(4.0	• •	• •			

All units in ug/l = parts per billion (ppb)

RSCL = Recommended Soil Cleanup Level

EPA HCL = Environmental Protection Agency Maximum Contaminant Level

EPA RHCL = Environmental Protection Agency Recommended Maximum Contaminant Levels

CADMS Act. Level = California Department of Health Services Actions Level

---- = Standard not defined for this compound

c = Concentration is below quantitation limit

.. = Not Detected

A copy of this section, as well as the calculations for determining applicable RSCL's and additivity derivations, are included in Appendix D. Using these criteria, it was determined that the VOC concentrations encountered in the soil at Integrated Specialties were significantly below the RSCL's.

Study of the field data (FID and PID) from the Bermed Area showed a slight rise in instrument readings as sample depth increased. To confirm that the presence of VOC's detected in this area is indeed significant, it is recommended that additional samples be collected from the area of B-8. These samples would be collected at depths greater than those attained at B-8, using a cart-mounted hollow-stem auger drilling rig.

Sample 43 collected from Boring B-14 at 4 inches (directly below the concrete pad) exhibited the highest instrument readings during project operations. The next sample, number 44, collected 8 inches below 43 shows considerably lower readings.

		Readings (ppm)					
Sample Number	Depth	PID	FID	IR			
43	4 inches	600	2000	785			
44	12 inches	90	70	< 1			

The concentration of VOC's in this boring location appears to be highest just beneath the concrete slab.

The analytical results for samples 52 and 53 suggest that the Electrical Transformer Pad is contaminated with low levels of PCB's. The level of PCB detected in a soil sample collected from the concrete pad itself was 4.4 ppm (Sample 52). The PCB concentration encountered in a soil sample collected from near the pad was 0.22 ppm (Sample 53). It appears that this is not a new spill nor is the concentration greater than 50 ppm. The volume of PCB containing material involved in this spillage appears to be less than one gallon. These factors preclude this spill occurrance from coming within the scope of the National PCB Spill Cleanup Policy (52 FR 10688) which became effective May 4, 1987. The policy imposes stringent standards for cleanup performance for Electrical Substations. The PCB Cleanup Level in soil is 25 ppm and on solid surfaces (i.e., the transformer pad) is 100 ug/100cm2.

Contact with the California Department of Health Services indicates that State policy is that the California action level for PCB's in soil is 50 ppm, according to Mardis Coers of the CADHS in a May 25, 1988 telephone conversation with BCLA. It therefore appears that no further sampling or remediation is required at this area.

Even though the State indicates that no action is required for this area, the owner may wish to inform the electric utility company which serviced Integrated Specialties of our findings. They may wish to initiate cleanup based on their own internal standards.

ŵ.

The runoff ditch has been shown to contain soil with elevated concentrations of Total Petroleum Hydrocarbons, (i.e., up to 2230 ppm). TPH is a California Regulated Waste. The CADHS has historically viewed surficial levels in excess of 1000 ppm as unacceptable. It is recommended that the runoff ditch be thoroughly cleaned of all accumulated soil. This soil is to be disposed of in a manner consistent with State standards. Verification samples should be collected at the conclusion of such cleanup activities to document that remaining soils do not contain unacceptable levels of TPH.

#### APPENDIX A

Engineer's Report on Groundwater Conditions

1983-84

4

ENGINEERS REPORT ON

GROUNDWATER CONDITIONS,


WATER SUPPLY AND BASIN UTILIZATION


IN THE ORANGE COUNTY WATER DISTRICT

ORANGE COUNTY WATER DISTRICT BOARD OF DIRECTORS

Kathryn L. Barr
John V. Fonley
Lawrence P. Kraemer, Jr.
Philip L. Anthony
Langdon W. Owen
Noble J. Waite
Donn Hall
John Garthe
August F. Lenain
Robert L. Clark

Neil M. Cline, Secretary Manager






#### 1985-86

# ENGINEERS REPORT ON GROUNDWATER CONDITIONS, WATER SUPPLY AND BASIN UTILIZATION IN THE ORANGE COUNTY WATER DISTRICT

# ORANGE COUNTY WATER DISTRICT BOARD OF DIRECTORS

Kathryn L. Barr
John V. Fonley
Lawrence P. Kraemer Jr.
Philip L. Anthony
Langdon W. Owen
Noble J. Waite
Donn Hall
John Garthe
August F. Lenain
Robert L. Clark

Nereus L. Richardson, Acting Secretary Manager



#### 1986-87

.


# ENGINEERS REPORT ON GROUNDWATER CONDITIONS, WATER SUPPLY AND BASIN UTILIZATION IN THE ORANGE COUNTY WATER DISTRICT

FEBRUARY 1988

# ORANGE COUNTY WATER DISTRICT BOARD OF DIRECTORS

Kathryn L. Barr
John V. Fonley
Lawrence P. Kraemer Jr.
Philip L. Anthony
Langdon W. Owen
Noble J. Waite
Donn Hall
John Garthe
August F. Lenain
Robert L. Clark

William R. Mills, Jr., General Manager



APPENDIX B

Зя

Boring Logs

HOLDCHEDN.

PROJECT NAME\_ 8-1. 88-524. PROJECT NUMBER\_ BORING DESIGNATION. DATE STARTED /-25-88 DATE F!NISHED PUTSION OF CLASTICE. 1.25.83 LOCATION COMPLETION DEPTH (FT) NUMBER OF 35" 3 DRILLER BC2 19 . SAMPLES WATER DRILLING ELEVATION GOND. DUGER. DEPTH (FT) EQUIPMENT AND DATUM DIAMETER AND TYPE OF WELL CASING LOGGED BY ROPLEZO. Sudde, DEPTH (FEET) B. E. Sample. DAT PFH. I SAMPLE NO. PIJHEMARKS IR. DESCRIPTION PTP FIP. 4" OF ASPHALT - IN YOUR COLLET Tion ( NO ( EAULS ) TRAVES OF AUPHALT **5**" 29 1/25 25 10 9.00 + 1 SAND (N) LIGHT CLIVE SCOWN CLEAN SAND. (2.57 56). MED. TO FINE LOOSE SAMP W/ SOME EILT . POORLY 96000 HOISTURE 12 12% 10 /S'-51<sup>1</sup> 7 30 15 SAND (W). CLIVE SICOUSN/2.5444). 9.05 1 10 CLEAN SAND. HED TO FINE SAUD WY SOME SILT-May . COMPACTED . PODALY ZP' GRADED : MOISTERE = 10% ŧ 25 14 30 10 6 30 DAND 30 SOUD LA BROUZ . 3 9.10-1 BCL1283-2

HELDEHLAN. PROJECT NAME\_ 88-524 BORING DESIGNATION. PROJECT NUMBER\_ OUT SIDE OF BERMED CONCRETE PAS DATE FINISHED 1.25-88 DATE STARTED 1-25-88 LOCATION GAST - WALL. NUMBER OF SAMPLES COMPLETION DEPTH (FT) 21 42" DRILLER BELLA. WATER DEPTH (FT) DRILLING ELEVATION AND DATUM HAND AUGER EQUIPMENT DIAMETER AND TYPE OF WELL CASING LOGGED BY ROS LAZ. JAN DE P. G. DEPTH (PEET) SAMPLE DATE PPM. SAMPLE NO. REMARKS DESCRIPTION PID FID 1" DEPHALT . IN GOOD COND. TOWN 6" CONCRETE . IN YOUR CONDI TION - NO CRACKS 25 Ş 10 9.40 1 SAND (W) OLIVE BLOWN (2.5746) MOD . COMPACTED FINE SILTY SAND. MOISTURE = 10% z4 80 14 10 9.45 . Bucha ca, enaz. clean sano. 51<sup>M</sup> 14 48 20 10. Jama, as ABOUTE. chean soms. Ġ 950 19 12. 13.15.0.5 11 - 13 LOND, AD ABOUTE CLUBA SAND. BCL1283 . 2

PROJECT NAME HOLACALAN B.3. 88-524. BORING DESIGNATION PROJECT NUMBER \_\_ OUT SIDE OF BERLIED CONCLETE PAD. 1-52-88 DATE STARTED /- 35-88 BORING FINISHED EAST WAll. COMPLETION DEPTH (FT) NUMBER OF 42" DRILLER 4 BCLA. SAMPLES WATER DEPTH (FT) DRILLING ELEVATION AND DATUM HAND AUGER EQUIPMENT DIAMETER AND TYPE OF WELL CASING LOGGED BY ROD LA 200 JAN DE DEPTH (FEET) SAMPLE. PEMARKS SAMPLE NO. DESCRIPTION PID FID. IL. I" DSPNAGT . SN OF CONCRETE IN 9000 י כ o condition. 9 21 10 1 20 28 9 1/35 1030 SAND WY OXIDATION SOND(W) YELLOWISH BROWN (RUST-LIKE) (104R 5/8) HED TO FINE WITH SAND HOD COMPACTED, POOLLY 9/10 Ed. MOTSUES 2-10% . SHOWS SOME OXIBATTON. 23 5H 18 24 47 10 1040 CLEAN SOND. SAND(W) OLIVE BOOWN (2.574/4) MOD COMPACTED, FINE SILTY SAMO MOISTAGE = 15% ર્ય 24 28 47 10 1050-1 ... SAUD, AS ADOUT 9 CLEAN SAND. ĺΦ 20 <7 15 14 SAND, AS EBOUE 11 1320 07 CLEDN SAND BCL1283-2

PROJECT NAME MOLACHLAN. 88-524 BORING DESIGNATION\_ PROJECT NUMBER\_ OUTSIDE OF BECHEO CONCRETE PAD. DATE DATE STARTED 1-25-88 1-25-88 LOCATION COST.WAII - IN EAST OF CLANFIER. NUMBER OF COMPLETION DEPTH (FT) 45" 4 BCLA. DRILLER WATER DEPTH (FT) DRILLING ELEVATION AND DATUM HAND BUGER. EQUIPMENT DIAMETER AND TYPE OF WELL CASING LOGGED BY 200.2470 Trade B 4. DEPTH (FEET) SAMPLE TIME PPM. DAT PPM PER PERAPES SAMPLE NO. DESCRIPTION PIV FIT IC. ی ت 10" OF ASPHALI IN good CORDI. , > TIGHT (NO CRAEKS). !/25 10+ 30 50 1100 + 1 SONDIWO OLIVE SYAM, MED. CLEAN SAND. LOOSE SAND WI SOME PROVEL. poorly grases. However 12% 30 60 10 11.10 SANS(W) OLINE GROW (25) 4/4). CLEAN SAND. MOD. COMPACTED, LINE SILTY SONS. Moisture = 10% 22. 32 47 SOME, AS ABOUT 10 11.20 / CLEAN EAND. 12 / Z SAND AL ABOUTE. 15 13.25 GLADZ LAND

MCLACHLAN PROJECT NAME \_\_\_ B.5. 88-524. BORING DESIGNATION. PROJECT NUMBER \_ BERNED CONCRETE PLD DATE FINISHED /- 25-88 DATE STARTED 1-25-88 BORING LOCATION HEAR THE EAST WALL (INSIDE) COMPLETION DEPTH (FT) NUMBER OF SAMPLES 32" DRILLER BCOA. WATER DEPTH (FT) DRILLING ELEVATION AND DATUM Heres sugal. EQUIPMENT DIAMETER AND TYPE OF WELL CASING LOGGED BY ROD, LAZS Trode SAMPLE . DEPTH (FEET) BG. PPM. X PPM. SAMPLE NO. PEREMARKS DESCRIPTION PID. FID TR 8" CONCRETE & GAS collection on swater CE But NO CRACKS. 0.02% 57 13 10 13.30 4.1.0 SICTT. CLATET SAND (W) OFIRE CLEAN FAMD (57 4/4). MOD COMPACTED without or proved. Naist-10% ۶M 190 1235 40 10 16 SILTY CLESEY SONS, as ACOUS + 17 CLEAN SAND 20 80 7 23 1340 1.0 SILTY. CLAYEY SAND, AS ABOVE 18 8 CLEAN JAND . BCL1283-2

HELDCHLAN PROJECT NAME\_ B-6 18-524. BORING DESIGNATION. PROJECT NUMBER\_ DATE DATE STARTED 1-25-88 BORING LOCATION FINISHED 1-25-88 NORTH . TOE 11,1 TONK AREA COMPLETION DEPTH (FT) NUMBER OF SAMPLES 300 DRILLER BELA WATER DEPTH (FT) ELEVATION AND DATUM DRILLING HAND AUGER. EQUIPMENT DIAMETER AND TYPE OF WELL CASING LOGGED BY ROD LAZO TENK PIT DEPTH (FEET) きょく かんき X PER REMARKS PPM. DESCRIPTION SAMPLE NO. PED FID TR 6" CONCRETE SLAS , IN GOOD COUNTRO M (NO CEALES). 142 0.028% 150 10 1.0 1/25 1400 CLEAN SAMD. SILTY CHAYEY SOND(W) OLIVE. ( ST 414). MOD. COMPACTED Moisture = 10% 15 154 190 143 1405 10 8 Silty Clayer Sand, as Adour. 20 clean sans. 5m 20 71 70 15 30 14.10-1.0 10 - SAND (W) OLIVE (574/4). CLEAN SAND. FINE TO VERY FINE LOOSESONS foodly grades. MAD. COMPACTED MOISTURE 15/19/6 ÞÖ. BCL1283-2

MCLOCHLAN PROJECT NAME \_\_\_ 88- 524. BORING DESIGNATION PROJECT NUMBER \_\_ BORING BEENED CONCETTE PAD WEST WALL AREA LOCATION OF THE EAST WALL (INSIDE). FINISHED 7-25-88 DATE DATE STARTED 1-25-88 NUMBER OF SAMPLES COMPLETION DEPTH (FT) 3011 DRILLER BC-LA. WATER DEPTH (FT) ELEVATION AND DATUM DRILLING HAND BUGER. EQUIPMENT DIAMETER AND TYPE OF WELL CASING LOGGED BY ROP LAZO SAMPLE. 8,6 DATE PPM. PPM. REMARKS SAMPLE NO. DESCRIPTION Fro FID .TR 3" CON CONTE PAD. IN YOUR ンマ constrient. for cracks? 3" CONCRETE PAD. ENGOD CONDITION ( NO CEAUS). 12 22 47 1/25 14.49 10 8 SAND (W) DLIVE YEllow ( 576/2) 22 CLEAN SAND. FINE TO VERY FINE LO-SE SAUS Poorly grades . MOISTHEY 10% 10 32 75 67 19.85- 10 23 SAND, DIABOUE . CLEAN SOND. SM 70 27 6Z 10 14.50 1.0 Sano (W) OLIVE (57 4/4) clear sans. MED. TO FINE SILTY SAND. Poorly grades. 409. Coupac TED, MOTETURE & 10%

PROJECT NAME HOLACHEAN. 88-524 BORING DESIGNATION. PROJECT NUMBER \_\_\_\_ DATE FINISHED 1-26-88 DATE STARTED /- 26.88 . BORING BEALES CONCRETE PAD INVIOLENST wall. NUMBER OF SAMPLES COMPLETION DEPTH (FT) 41" 4 BCLA . DRILLER WATER DEPTH (FT) ELEVATION AND DATUM DRILLING NAND AUGER. EQUIPMENT DIAMETER AND TYPE OF WELL CASING LOGGED BY LOW LA W Trede, SEMPLE. 86. TIME FEM. PPM REMARKS SAMPLE NO. DESCRIPTION IK PID FID 5" CONCRETE SLOS. WISHEREE 2 7 CONCORDE BUT NO ERADES. 40 7 12 855 | I 1/22 10 CLEAN SANS. Sans (w) Olive seed to Five 25 SLUS WISOME SIRT. MOSS. COM. PACTED GOODING GLOSS MISTERS 60 7 SOUD, BLAGOUTE. 16 10 26 1 900 CLEAN SAME. 37 20 28 30 445 10 -9.05 27 CLEAN SAND. - SAMDIAS ABOUT 37 נאני פעי 120 0.03% 67 10 1500 57 SAND, AS ABOUT CLEAN SAND. BCL1283-2

PROJECT NAME MCLACHEAN. PROJECT NUMBER 88-524. B-9. BORING DESIGNATION. DATE STARTED 7-26-8 \$ FINISHED \$ 26.88 DATE BORING BERNES COMMERCE PAS SUSTON EACT NUMBER OF COMPLETION 28" 3 DRILLER BCLR. WATER DEPTH (FT) DRILLING ELEVATION AND DATUM HAND AUGER. EQUIPMENT DIAMETER AND TYPE OF WELL CASING LOGGED BY Rolas (Jrktos) BG. DEPTH (FEET) SAMPLE. PPM E PES ETS SAMPLE NO. DESCRIPTION PTO FID 12. 4" CONCRETE SLAB MY COPENSION but so chacks 1/26 50 47 4.20 -1 - 24 10 28 SAND (W) OLIVE (SY4/4) HEX TO ر هدمي درمي FINE SUND WY SOME SICT. MOD. COMPACTED. PORLY GODDED. MOISTURE = 10% 58 .30 < 7 29 SAUD AS AROJE .9.75 10 CLEAN GAND 32 100 =7 30 10 SAND, AS ABOUT . 9.30 1 CLEAN SAUD. BCL1283-2

HeLacHAN.

PROJECT NAME\_ B-10 88-524. PROJECT NUMBER. BORING DESIGNATION. BORING BEALLED CONCRETE POD, EXECUTE LOCATION BAST WORK. FINISHED 1. 26-88 . DATE STARTED 1.26-88 COMPLETION DEPTH (FT) NUMBER OF 28" DRILLER BOLA. SAMPLES WATER DRILLING ELEVATION AND DATUM HAND. AUGER . DEPTH (FT) EQUIPMENT DIAMETER AND TYPE OF WELL CASING LOGGED BY ROS. ALSO Trada DEPTH (FEET) SAMPLE 136. DAT ppin. 1974 FID. FID === SAMPLE NO. PERMERS DESCRIPTION  $\mathcal{I}$  .  $\mathcal{C}$ 4" CONCRETE SULLY, WICOMOSIONS BUT NO CROCKS. 7 80 35 1/26 10 9.00 1 3) CLEAN SAND. SONOTHING OLIVE (574/4). ped. to pind goud w/ BOME Sict-MED. COMPACTED, PODELY GRADES. MOTEURE = 10%. 15" 12 40 49 SAND AS ABOUT 9-41 10 32 clean sand. 40 80 27 9.50 -1 10 SLAD AS ABOUTE . CLEAN SAMLE 33 26 BCL1283-2

PROJECT NAME He LACHEN 3-11 88-254 PROJECT NUMBER BORING DESIGNATION. BERMES CONCRETE PAR. DATE FINISHED 1.26 88 BORING LOCATION DATE STARTED 1-26-83 EAST- WALL ENSIDE COMPLETION DEPTH (FT) NUMBER OF SAMPLES 31" DRILLER 3 BOLA. WATER DEPTH (FT) DRILLING HAND AUGER. EQUIPMENT AND DATUM DIAMETER AND TYPE OF WELL CASING LOGGED BY KOD LE W Trade DEPTH (FEET) C 😽 . SAMPLE DATE PPH. REMARKS SAMPLE NO. DESCRIPTION F PIN FIN IN. 12" CONCRETE SLATS. W/SOME Coccosion BUTNO CRACES ", Įφ'. c 1/26 25 40 < ? 10 10.00 34. 50 ND (W) OLIVE (57 4/4). CREWN SYME. HED. TO FINE SAND WISHE SILT HOR CORPACTED. Yoully grages. HOI SWEETE'S 10 30 80 =8 135 1005 FUDBA ZA CUAZ 5M CLEAN SAND. 60 150 مرس 1010/ 10 SUNDING DOODE 36 CLEAN SOND. 'ن بن

PROJECT NAME MCLACHLAN 8-12. 88-524. BORING DESIGNATION\_ PROJECT NUMBER\_ BORING BELLED CONCRETE PAD LOCATION TOCOT DATE FINISHED 1-26-88. DATE STARTED 1-26-28 COMPLETION DEPTH (FT) NUMBER OF SAMPLES 31" DRILLER BELA. WATER DEPTH (FT) DRILLING ELEVATION AND DATUM HAND BUGER. EQUIPMENT DIAMETER AND TYPE OF WELL CASING LOGGED BY LOU LAZG BG. SAMPLE PFMI. PPM. DESCRIPTION SAMPLE NO. PT9 REMARKS PID PID. IR. ÷. 6" CONCRETE SLAB WISOME CORROSON GUT NO CROCKS ٥ D 6" Concluse Slady in good っ ,= **\*** CONDITION 00 15 40 67 10 37 1/20 SAUDIW DLIVE (5) 4/4) CLEARS CLASS 10.40 HED TO FINE SAME MYSOME SILT. NOW. CONTRACTED. Prostly grades . Hoist = 10% 20 60 49 5M 10.45 10 CLEAN SAND 38 SAND, AS AGOUT 13 D' 30 80 =7 10. SAND PAS ABOJE. 10,50 clean Samo 39. ŧ BCL1283-2

Me LACITLANS. PROJECT NAME\_\_ 88-534. B-13. PROJECT NUMBER\_ BORING DESIGNATION. DATE STARTED 1.26.88 DATE BORING NEAR (TCE) TANK . NEAR CONTER OF Guilsin LOCATION NUMBER OF SAMPLES COMPLETION DEPTH (FT) DRILLER BCLA. 300 3 WATER DEPTH (FT) DRILLING ELEVATION AND DATUM HAND HUYER. EQUIPMENT DIAMETER AND TYPE OF WELL CASING LOGGED BY Fronte 15 B-13 DEPTH (FEET) BG. Sample. FPM. DESCRIPTION SAMPLE NO. PI TEMARKS PIV FID TR. 6" CONCRETE. IN YOUR CONTACTO .U. 0 <u>ال</u>اخا 8 9 15 30 14 101 1/26 40 17.10 SAND (W) LIGHT OLIVE CLEAN SAND. MOWN (2.57 (4), MED. 70 FINE GODE SAND BOOKLY GRODED MOTSTURE - 10% 70 85 SAND [W) Pole YEllow (2547/2) 41 35 11.15 1 10 CLEAN JAND MED. TO CONESE SAND LONE AND DRY NOD. GRADED. 30 50 14 10 1105M SAND, AS A BOUTE 30 42 CEAN DAYS. BCI 1283-2

3.

MCLACHEAN.

PROJECT NAME\_ 88-524 BORING DESIGNATION. PROJECT NUMBER\_ DATE FINISHED DATE STARTED 1- 26. 88 1.26-88 BORING LOCATION cooling wares . حرسس COMPLETION DEPTH (FT) NUMBER OF ģ 326A 4 DRILLER SAMPLES WATER DEPTH (FT) DRILLING ELEVATION AND DATUM AUGER HANS EQUIPMENT DIAMETER AND TYPE OF WELL CASING EDIT OF COOLING LOGGED BY KOD LOG TANK. .. JAN OF DEPTH (FEET) 13,6. SAMPLE REMARKS 17474 SAMPLE NO. DESCRIPTION PED FEE. 4" CONCACTE SIAG (NO CRACES) 600 0.2% 785 10 1/26 1300 SAUD (W) OLIVE B/BOWN (2.5) 4/4) 43 clean sous. FINE TO USBY FINE SICTY 90 70 27 13 5 1, LI 10 ر درود ندوین SAND MOD. COMPACTED, POORLY GRADED. MOISTURE = 10%. 110 150 10 23 14 - E LOS AL ASOU ET 45 1312 1 ELEAN SAMO. 100 70 27 10 3 1315 L / SUNDAL AGOUT 40 CLEAN SAND. 27 25 20 1322 1 10 47 Thought brong. CCEAN SAND. ×Μ 15 20 10 14 1335 1 48 SALUDIAS ABOUE. CLEAN SANS. 20 15 < 7 18 STAND IT ABOLE. 1339 / 49 CLEAN SHAME 25 25 KT 10 SAMBIAS ASOUTE 1335 50 clean Sand 10 60 67 SANDIWI LIGHT OLINE BROWN . 51 1340+ 1 10 CLEAN SLUB. (2.5) 5%) LINE TO VELY 13 FIRE LOOSE SONO, 900 Rby. guares. Moisture = 10% 9CL1283-2

## BORING LOG AND SAMPLING RECORD

PAGE! OF ONE

HE LACHEAN PROJECT NAME. B-15 88.524 BORING DESIGNATION. PROJECT NUMBER. DATE FINISHED 1. 26-88 ECE CTICLE DATE 126.88 BORING LOCATION West END OF CONDRETE PAD ( TEMPORE NUMBER OF SAMPLES COMPLETION DEPTH (FT) 24" DRILLER ECCA. WATER DEPTH (FT) -DRILLING ELEVATION AND DATUM HOND DUSER. EQUIPMENT DIAMETER AND TYPE OF WELL CASING ON PLANTER LOGGED BY LOD LOEA B 5. SAMPLE PPM. REMARKS DEPTH (FEET) TIME DAT PPM SAMPLE NO. DESCRIPTION PIP FID 110 SAND (W7 OLIVE SCOUNT (25)4/4) 53 1/26 10 100 Oleman Samo, FINE TO VERY FINE SILTY SAND. HOD COMPACTOS, MOI STURE J 13 2/2 12 14 10 5 10 1405 CLEON SAND. 54 SANSA AL ABOUTE! 12 27 1419-1 5 10 SAND, A. ABOJE 55 CLEDN JAND BCL1283-2


#### APPENDIX C

Laboratory Analytical Reports



## BCL ASSOCIATES, INC.

Planners • Engineers • Scientists • Chemists



5702 Bolsa Avenue, Huntington Beach, CA 92649 / (714) 892-2565 (213) 437-4148

#### LABORATORY REPORT

Report	to: BCL Associates, Inc.	
	5702 Bolsa Ave.	
	Huntington Beach, CA 92649	

88-524 Client Number: 00078 Laboratory Number: 2/22/88 Report Date: 1/26/88 Received Date:

Purchase Order No.:\_

Attention: Jim Severns

Sample Description: Seven soil samples

Testing Methods:

pH/EPA method 9045; TTLC metals/ICP & AA, Title 22;

GC/MS, EPA Method 8240

BCL #	Client Sample #	Test	Results (mg/Kg)	Analyst	Date of Analysis
38-0078-001	#1	pН	9.4	NY	1/29
38-0078-004	#4	PН	10.2	NY	1/29
38-0078-007	<b>#</b> 7	pН	11.4	ИА	1/29
38-0078-010	#10	рН	9.2	NY	1/29
38-0078-016	#16	pН	8.7	NY	1/29
38-0078-019	#19	8240	*	JK	*
		рН	10.1	NY	1/29
38-0078-022	#22	511	20.2		

\* See attached summary sheets.

Beth Riley

Environmental Chemist

3.48F1.R60

Steve Jones, Ph.D. Laboratory Manager

B C L Analytical Laboratories	5702 Bolsa Avenue Huntington Beach, CA	92649 (714) 892-2565
A	NALYTICAL RESULTS SUMMARY AA and ICP Analyses	
Client Name: BCL Associates, Inc. Client Job Number: 88-524 Project Name: McLachlan Laboratory Supervisor Approval:	Client (Field) Sample No.:  Date Collected:  Date Received (in lab):  Date Analyzed:	1-25-88 1-26-88
Sample Matrix:	Dilution Factor: Extraction Method:	EPA 3050
Water (milligrams per liter)  X Soil (milligrams per kilogram)	Lab Sample No.:	00078
Other (annify)		

	Threshold	Threshold		TILC	#10	#16	#22 38-00078-
	Level	Level		Detection	38-00078-	38-00078-	
Elements	STLC	TTLC	Method	Limit	010	016	022
Antimony, Sb	1.5	500	6010	0.6	שט	ND	ND
Arsenic, As	5.0	500	7060	0.3	6.3	8.3	2.9
Barium, B	100	10,000	6010	2	56	88	70
Beryllium, Be	0.75	75	6010	0.1	0.35	0.39	0.35
Cadmium, Cd	1.0	100	6010	O. I	ND	0.21	ND
Chromium, Cr	51.0	2,500	6010	0.2	16	22	20
Cobalt, Co	80	8,000	6010	1	5.4	35	5.8
Copper, Ou	25	2,500	6010	0.4	9.2	38	8.1
Lead, Pb	5.0	1,000	7421	0.2	27	29	2.5
Mercury, Hg	0.2	20	7471	0.09	ND	ND	ND
Molybdenum, Mo	350	3,500	6010	0.2	1.3	2.6	1.9
Nickel, Ni	20	2,000	6010	0.8	11	120	13
Selenium, Sc	1.0	100	7740	0.6	ND	ND	ND
Silver, Ag	5	500	6010	0.2	10	12	11
Thallium, Tl	7.0	700	6010	0.6	ND	ND	ND
Vanadium, V	24	2,400	6010	1	44	50	44
Zinc, Zn	250	5,000	6010	0.1	43	68	44

 $N\!\mathbb{D}$  - none detected

 $\mathcal{F}_{q}^{+}$ 

1

TR - trace, below detection limit

Page 2 of 2

3.48G.ARS-60.1

)	B C L Analytical Laboratories 5702 B	olsa Avenue Huntington Beach, CA	92649 (714) 892-2565
		al results summary	
	AA. and	d ICP Analyses	
	Client Name: BCL Associates, Inc.	Client (Field) Sample No.:	
	Client Job Number: 88-524		1-25-88
	Project Name: McLachlan	Date Received (in lab):	1-26-88
	Laboratory Supervisor Approval:	Date Analyzed:	
	Date:		•
		Dilution Factor:	
	Sample Matrix:	Extraction Method:	EPA 3050
**	Water (milligrams per liter)	Lab Sample No.:	00078
ere.	X Soil (milligrams per kilogram)		
A.	Other (specify)		

	Threshold	Threshold		TTLC	#1	#4	#7
	Level	Level.		Detection	38-00078-	38-00078-	38-00078-
Elements	STLC	TTLC	Method	Limit	001	004	007
Antimony, Sb	1.5	500	6010	0.6	ND	ND	ND ND
Arsenic, As	5.0	500	7060	0.3	2.7	1.9	4-6
Barium, B	100	10,000	6010	2	64	93	53
Beryllium, Be	0.75	75	6010	0.1	0.25	0.42	0.32
Cadmium, Cd	1.0	100	6010	0.1	0-47	0.56_	ND
Chromium, Cr	51.0	2,500	6010	0.2	14	21	45
Cobalt, Co	80	8,000	6010	1	4.3	19	12
Copper, Or	25	2,500	6010	0.4	6-1	16	42
Lead, Pb	5-0	1,000	7421	0.2	2.6	3.2	8-1
Mercury, Hg	0.2	20	7471	0.09	ND	ND	ND
Molybdenum, Mo	350	3,500	6010	0.2	1-6	2.5	4.6
Nickel, Ni	20	2,000	6010	0.8	12	320	150
Selenium, Se	1-0	100	7740	0.6	ND	ND	NO
Silver, Ag	5	500	6010	0.2	9.4	. 14	9.9
Thallium, Tl	7.0	700	6010	0.6	ND	ND	ND
Vanadium, V	24	2,400	6010	1	38	53	56
Zinc, Zn	250	5,000	6010	0-1	24	60	69

ND - none detected

TR - trace, below detection limit

Page 1 of 2

3.48G.ARS-60

## VOLATILE ORGANICS ANALYSIS DATA SHEET

	BCLA	LAB	NO.
   	#19		

b Name: BCL ASSOCIATES

Job No.:88-524

Hatrix: (soil/water) SOIL

Sample No.: 00078-006

Sample wt/vol:

5.5 mL

Data File ID:

>2AAK4

Date Received: 01/26/88

Date Analyzed: 2/05/88

ilution Factor: 1

CAS NO.	COMPOUND	ONCENTRATION UNI	
	COMPOUND	ug/Kg	Q
74-87-3	Chloromethane	10.	ΙU
74-83-9	Bromomethane	10.	Ū
75-01-4	Vinyl Chloride	10.	ĺυ
75-00-3	Chloroethane	10,	ĺυ
75-09-2	Methylene_Chloride	1 70.	ΙB
67-64-1	Acetone	1 19.	I B
/5-15-0	Carbon Disulfide		iυ
75-35-4	1,1-Dichloroethene	1 5.	וֹטו
75-34-3	1,1-Dichloroethane	5.	เบ
67-66-3	Chloroform	1 5.	18
107-02-2	1,2-Dichloroethane	1 .5	ĺΤ
78-93-3	2-Butanone	1 21.	I B
71-55-6	1,1,1-Trichloroethane	. 9	iT
56-23-5	Carbon Tetrachloride	. 1 . 4	T
108-05-4	Vinyl Acetate_	1 10.	ΙŪ
75-27-4	Bromodichloromethane	! .4	1 T
78-87-5	1,2-Dichloropropane	i 5.	U
10061-01-5	cis-1,3-Dichloropropene	1 5.	เบ
79-01-6	Trichloroethene	2.	T
124-48-1	Dibromochloromethane	1 5.	ΙÜ
79-00 <b>-</b> 5	1,1,2-Trichloroethane	5.	โบ
71-43-2	Benzene	2.	ΙΤ
10061-02-6	trans-1,3-Dichloropropene	1 5.	įυ
75-25-2	Bromoform	5.	ΙŪ
108-10-1	4-Methyl-2-pentanone_	9.	İT
591-78-6	2-Hexanone	14.	i B
127-18-4	Tetrachloroethene	7.	i
79-34-5	1,1,2,2-Tetrachloroethane	5.	iυ
108-88-3	Toluene		เช
108-90-7	Chlorobenzene	, 6	ΙΤ
100-41-4	Ethylbenzene	. 9	ÎT
100-42-5	Styrene	1 4.	IT
133-02-7	Xylene (total)	i	Ü

U = Compound undetected. Concentration listed is detection limit.

Page 1 of 1

T = Trace amount, Concentration is below detection limit.

B = Found in blank.



### BCL ASSOCIATES, INC.

Planners • Engineers • Scientists • Chemists



5702 Bolsa Avenue, Huntington Beach, CA 92649 / (714) 892-2565 (213) 437-4148

#### LABORATORY REPORT

Report to:	BCL Associates, Inc.	Client Number:	88-524 00081
	5702 Bolsa Ave.	Laboratory Number: Report Date:	2-10-88
•	V	Received Date:	1-27-88
•	Huntington Beach, CA 92649	Purchase Order No. :	
- 	James Severns		

Sample Description:

10 soil samples

Testing Methods:

pH/EPA method 9045; EPA 3050/TTLC Metals (Title 22); EPA

8240; EPA 8080

BCL #	Client Sample #	Test	Results	Analyst	Date of Analysis	Reporting Limit
38-00081-001	25	pН	8.6	NY	1/29	
		TTLC	*	BR	2/1	*
38-00081-002	28	pН	8.1	NY	1/29	
		TTLC	*	BR	2/1	_ <u>*</u>
38-00081-003	31	На	8.0	NY	1/29	
		TTLC	*	BR	2/1	*
38-00081-004	34	рН	9.6	NY	1/29	
		TTLC	*	BR	2/1	*
38-00081-005	37	pН	9.1	NY	1/29	
		TTLC	*	BR	2/1	*
38-00081-006	41	8240	*	JK	2/5	*

\* See attached sheets.

Beth Riley

Environmental Chemist

Steve Jones, Ph.D.

Lab Manager

3.48F.R59

### LABORATORY REPORT (continued)

BCL #	Client Sample #	Test	Results	Analyst	Date of Analysis	Reporting Limit
38-00081-007	43	Щq	9.3	ΝY	1/29	
		8240	*	JΚ	2/5	*
		TTLC	*	BR	2/1	*
		8080				
38-00081-008	52	(PCB's)	4.4 ppm	RB	2/9	0.8 ppm
		8080				
38-00081-009	53	(PCB's)	0.22 ppt	n RB	2/9	0.008 ppm
38-00081-010	57	8240	*	JK	2/5	*

<sup>\*</sup> See attached sheets



3.48F.R59.1

B C L Analytical Laboratories	5702 Bolsa Avenue	Huntington Beach, C/	A 92649 (714) 892-2565
	AMALITICAL RESILIS SI AA and ICP Analyse		
Client Name: BCL Associates, Ir Client Job Number: 88-524 Project Name: McLachlan Laboratory Supervisor Approval: Date:	late (	c (Field) Sample No.: Collected: Ceceived (in lab): Unalyzed:	1-26-38 1-27-88
. Sample Matrix:		ion Factor: ction Method:	EPA 3050
Water (mlcrograms per liter)	Lab Se	mple No.:	00081
X Soil (micrograms per kilogram) Other (specify)			

	Threshold	Threshold		TELC	<b>#</b> 25	#28	#31
	level	<b>Level</b>		Detection	38-00081-	38-00081-	38-00081-
Elements	STLC	TTLC	Method	Limit	001	002	003
Antimony, Sb	1.5	500	6010	0.6	ND	ND	ND
Arsenic, As	5.0	500	7060	0.3	4.0	2.7	4.7
Barium, B	100	10,000	6010	2	110	104	92
Beryllium, Be	0.75	75	6010	0.1	0.47	0.48	0.43
Cadmium, Cd	1.0	100	6010	0.1	0.57	0.17	0.19
Chromium, Cr	51.0	2,500	6010	0.2	36	27	24
Cobalt, Co	80	8,000	6010	1	7.4	22	9.2
Copper, Cu	25	2,500	6010	0.4	14	13	11
Lead, Pb	5.0	1,000	7421	0.2	8.7	7.6	16.7
Mercury, Hg	0.2	20	7471	0.09	ND	ND	ND
Molybdenum, Mo	350	3,500	6010	0.2	3.3	2.4	2.2
Nickel, Ni	20	2,000	6010	0.8	22	18	15
Selenium, Se	1.0	100	7740	1.6	ND	ND	NTD
Silver, Ag	5	500	6010	0.2	16	17	15
Thallium, Tl	7.0	700	6010	0.6	ND	ND	ND
Vanadium, V	24	2,400	6010	1	69	67	58
Zinc, Zn	250	5,000	6010	0.1	60	59	54

ND - none detected

TR - trace, below detection limit

Page 1 of 2

g.

3.48G.ARS-59

B C L Analytical Laboratories 5702 Bolsa	Avenue Hintington Beach, CA 92649 (714) 892	-2565
; ; ; ;	esults sumary ? Analyses	
Client Name: BCL Associates, Inc. Client Job Number: 88-524 Project Name: McLachlan Laboratory Supervisor Approval: Date:	Client (Field) Sample No.: Date Collected: 1-26-88 Date Received (in lab): 1-27-88 Date Analyzed:	
Sample Matrix	Dilution Factor: Extraction Method: EPA 3050	
Water (micrograms per liter)  X Soil (micrograms per kilogram)	Lab Sample No.: 00081	
Other (specify)	_	

	Threshold	Threshold		TTLC	#34	#37	#43
	Level	Level		Detection	38-00081-	38-00081-	38-00081-
Elements	STLC	TTLC	Method	Limit	004	005	007
Antimony, Sb	1.5	500	6010	0.6	ND	ND	ND
Arsenic, As	5.0	500	7060	0.3	2,5	3.0	7.1
Barium, B	100	10,000	6010	2	5.3	102	83
Beryllium, Be	0.75	75	6010	0.1	1.2	0.47	0.40
Cadmium, Cd	1.0	100	6010	0.1	ND	0.31	0.87
Chromium, Cr	51.0	2,500	6010	0.2	29	27	79
Cobalt, Co	80	8,000	6010	1	15	7.2	6.5
Copper, Cu	25	2,500	6010	0.4	50	12	12
Lead, Pb	5.0	1,000	7421	0.2	33	9.1	42
Mercury, Hg	0.2	20	7471	0.09	ND	ND	ND
Molybdenum, Mo	350	3,500	6010	0.2	2.1	2.7	2.5
Nickel, Ni	20	2,000	6010	0.8	220	17	15
Selenium, Se	1.0	100	7740	1.6	ND	ND	ND
Silver, Ag	5	500	6010	0.2	17	17	13
Thallium, Tl	7.0	700	6010	0.6	ND	ND	ND
Vanadium, V	24	2,400	6010	1	55	69	52
Zinc, Zn	250	5,000	6010	0.1	160	60	160

ND - none detected

TR - trace, below detection limit

Page 2 of 2

4

3.48G.ARS-59.1

#### 1A VOLATILE ORG ICS ANALYSIS DATA SHEET

41

JOB SAMPLE NO.

ab Name: BCL ASSOCIATES Job No.:88-524

fat ix: (soil/water) SOIL

Lab Sample ID: 00081-006

umple wt/vol:

5.11 g Lab File ID:

>2AAK5

Date Received: 01/27/88

ite Analyzed: 2/05/88

:.

"llution Factor: 1.0

CONCENTRATION UNITS:

CAS NO.	COMPOUND (u	g/L or ug/Kg) ug/Kg	<u> </u>
74-83-9	Bromomethane	10.	   U
75-01-4	Vinyl Chloride	10.	П
75-00-3	Chloroethane	10.	ען
75-09-2	Methylene_Chloride_	5,	U
67-64-1	Acetone	10.	บ
75-15 <b>-</b> 0	Carbon Disulfide	5.	U
75-35-4	1,1-Dichloroethene	5.	Ū
75-34-3	1,1-Dichloroethane		Ū
67-66-3	Chloroform	5.	ប
107-02-2	1,2-Dichloroethane	5.	Ü
78-93-3	2-Butanone	10.	ÜΪ
71-55-6	1,1,1-Trichloroetha	ne 1.	T
56-23 <b>-</b> 5	Carbon Tetrachloride	e	Ū
108-05-4	Vinvl Acetate	37.	ì
75-27-4	Bromodichloromethan	e 5.	jυ
78-87-5	1,2-Dichloropropane	5.	U
10061-01-5	cis-1,3-Dichloropro	pene 5.	U
79-01-6	Trichloroethene		U
124-48-1	Dibromochloromethan	e 5.	ľŬ
79-00-5	1,1,2-Trichloroethan	ne 5.	וטן
71-43-2	Benzene	l 5.	U
10061-02-6	trans-1,3-Dichlorop	ropene  5.	U
75-25-2	Bromoform	<u> </u>	U
108-10-1	4-Methyl-2-pentanone	e 10.	U
591-78-6	2-Hexanone	10.	
127-18-4	Tetrachloroethene	[ 5.	ľŪ
79-34-5	1,1,2,2-Tetrachloro	ethane 5.	U
108-88-3	Toluene		וַען
108-90-7	Chlorobenzene	5.	ĮŪ
100-41-4	Ethylbenzene	5.	Įΰ
100-42-5	Styrene	5.	បែ
133-02-7	Xylene (total)	5.	U

T = TRACE AMOUNT, BELOW DETECTION LIMIT

U = NOT DETECTED AT SPECIFIED DETECTION LIMIT

B = FOUND IN BLANK

ab Name: BCL ASSOCIATES

Job No.:88-524

Ma.\_ix: (soil/water) SOIL

Lab Sample ID: 00081-007

ample wt/vol:

5.92

Lab File ID:

>2AAK6

Date Received: 01/27/88

ate Analyzed: 2/05/88

 $\frac{1}{2}\sqrt{2}$ 

 $\lesssim$ 

ilution Factor: 1.0

CONCENTRATION UNITS:

CAS NO.			rug/Kg)		Q
74-83-9	Bromomethane			10.	U
75-01-4	Vinyl Chloride			10.	ប
75-00-3	Chloroethane			10.	ĮŪ
75-09-2	Methylene Chloride			280.	BE
67-64-1	Acetone	<del></del>		10.	U
75-15-0	Carbon Disulfide			5.	ט
75-35-4	1,1-Dichloroethene		<del></del> ;	5.	Ü
75-34-3	. 1,1-Dichloroethane			5.	Ü
67-66-3	Chloroform		¦	5.	Ū
107-02-2	1,2-Dichloroethane		<del></del> ¦	5.	Ū
78-93-3	2-Butanone	<del> `</del>	<del></del> ¦	10.	Ü
71-55-6	1,1,1-Trichloroethan	20	·	2.	T
56-23-5	Carbon Tetrachloride		¦	2. 5.	{ <b>Ü</b>
108-05-4	Vinyl Acetate	<b></b>	¦	10.	U
75-27-4	Bromodichloromethane		<del></del> ¦	5.	U
78-87-5	1,2-Dichloropropane		<del></del> ¦	5.	[ [ ]
10061-01-5	cis-1,3-Dichloroprop	neme.		5.	טו
79-01-6	Trichloroethene	, c.i.c	<del></del> ¦	2.	∤T
124-48-1	Dibromochloromethane			5.	Ü
79-00-5	1,1,2-Trichloroethar			5.	U
71-43-2	Benzene		<del></del> -	3.	T
10061-02-6	trans-1,3-Dichloropi	conene		5.	Ü
75-25-2	Bromoform	. Opene		5.	טן
108-10-1	4-Methyl-2-pentanone		<del></del> ¦	10.	ΙŪ
591-78-6	2-Hexanone		¦	10.	}Ω io
127-18-4	Tetrachloroethene		<u> </u>	31.	[0
79-34-5	1,1,2,2-Tetrachloroe	+2220		5.	   U
108-88-3	Toluene	critaire			1 -
108-88-3	Chlorobenzene		<del></del> ¦	5.	Ū
100-41-4	Ethylbenzene			5.	U
100-41-4			!	1.	T
133-02-7	Styrene (total)		!	5.	U
	Xylene (total)			5.	Ŭ

T = TRACE AMOUNT, BELOW DETECTION LIMIT

U = NOT DETECTED AT SPECIFIED DETECTION LIMIT

B = FOUND IN BLANK

## VOLATILE ORG. ICS ANALYSIS DATA SHEET

JOB SAMPLE NO.

.b Name: BCL ASSOCIATES

Job No.:88-524

Lab Sample ID: 00081-010

mple wt/vol:

at\_ix: (soil/water) SOIL 5.38

g

COMPOUND

>2AAK7

Lab File ID:

ate Received: 01/27/88

te Analyzed: 2/05/88

ilution Factor: 1.0

CAS NO.

CONCENTRATION UNITS:

(ug/L or ug/Kg) ug/Kg

Q

	(45, 2 02 45)	1	
74-83-9	Bromomethane	10.	I IU
75-01-4	Vinyl Chloride	10.	Ü
75-00-3	Chloroethane	10.	ט
75-09-2	Methylene_Chloride	86.	B
67-64-1	Acetone	10.	U
75-15-0	Carbon Disulfide	5.	Įυ
75-35-4	1,1-Dichloroethene	5.	ען
75-34-3	1,1-Dichloroethane	5.	įυ
67-66-3	Chloroform	5.	ប់
107-02-2	1,2-Dichloroethane	5.	iυ
78-93-3	2-Butanone	10.	បែ
71-55-6	1,1,1-Trichloroethane	5.	i
56-23-5	Carbon Tetrachloride	5.	iυ
108-05-4	Vinyl Acetate	10.	์ บั
75-27-4	Bromodichloromethane	5.	Ü
78-87-5	1,2-Dichloropropane	5.	Ū
10061-01-5	cis-1,3-Dichloropropene	5.	iυ
79-01-6	Trichloroethene	13.	i -
124-48-1	Dibromochloromethane	5.	iυ
79-00-5	1,1,2-Trichloroethane	5.	ี่บั
71-43-2	Benzene	2.	T
10061-02-6	trans-1,3-Dichloropropene	5.	Ü
75-25-2	Bromoform	5.	บ
108-10-1	4-Methyl-2-pentanone	10.	ี้ขั
591-78-6	2-Hexanone	10.	ĺΰ
127-18-4	Tetrachloroethene	27.	i
79-34-5	1,1,2,2-Tetrachloroethane	5.	ប
108-88-3	Toluene	5.	Ū
108-90-7	Chlorobenzene	5.	Ū
100-41-4	Ethylbenzene	5.	ี่บั
100-42-5	Styrene	5.	Ū
133-02-7	Xylene (total)	5.	เบ

T = TRACE AMOUNT, BELOW DETECTION LIMIT

U = NOT DETECTED AT SPECIFIED DETECTION LIMIT

B = FOUND IN BLANK



## BCL ASSOCIATES, INC.

Planners • Engineers • Scientists • Chemists



, v

5702 Bolsa Avenue, Huntington Beach, CA 92649 / (714) 892-2565 (213) 437-4148

#### REPORT LABORATORY

		LADORIL		
Report to:	BCL Associ	ates, Inc.	Client Number: Laboratory Number:	88-524 00307
•	5702 Bolsa		Report Date:	07/06/88 06/28/88
•	Huntingtor	Beach, CA	Received Date:	
•			Purchase Order No.	
Attention:	James J.	Severns		
Sample Des	cription:	Twelve soil samp	les in 250 ml glass jars	
Testing Me	ethods:	STLC Arsenic, Ba Silver, Vanadiu 6010 and 7421	rium, Beryllium, Copper, mm/ICP + AA; CAC WET Titl	Lead, Nickel, e 22/EPA 7060,
Results fo	or the meta	ls analysės are (	on the following summary	sheets.

Jesus Mallari Technical Director

Environmental Chemist

3.48F1.R261

#### ANALYTICAL RESULTS SUMMERY CAM Title 22 Metals AA and ICP Analyses

, AIV

المنتصل المساب

: .

Client Name: BCL Associates, Inc. Client Job Number: 88-524 Project Name: McLachlan	Lab Receiving No.: 00307  Date Collected: 06/28/88  Date Received (in lab): 06/28/88
Sample Matrix:	Extraction (soils only): STLC
Water (milligrams per liter)	
Soil (milligrams per kilogram)	
X Other (specify) CAC WET Extract	

J-50 131.

Elements	Date Analyzed	Threshold Level STLC (mg/L)	Threshold Level TILC (mg/Kg)	Method	SILC Detection Limit (mg/L)	TILC Detection Limit (mg/Kg)	BCL #1 38-00307 001 (mg/L)	BCL #4 38-00307 002 (mg/L)	BCL #7 38-00307 003 (mg/L)	BCL #10 38-00307 004 (mg/L)	BCL #16 38-00307 005 (mg/L)	BCL #22 38-00307 006 (mg/L)
ntimony, Sb wsenic, As	07/05/88 07/05/88	1.5 5	500 500	6010 7060	0.03 0.02					0.28	0.15	
larium, Ba	07/05/88	100	10000	6010	0.02							
eryllium, Be	07/05/88	0.75	75	6010								
ladmium, Cd	07/05/88	1	100	6010								
hronium, Cr	07/05/88	51	2500	6010								
Cobalt, Co	07/05/88	<b>8</b> 0	8000	6010	0.01				0.69		3.3	.*
Copper, Cu	07/05/88	25	2500	6010	0.01				TR	2.0	1.l	
ead, Pb	07/05/88	5	1000	6010	0.2							
Mercury, Hg	07/05/88	0.2	20	7471								
folybdenum, Mo	07/05/88	250	3500	6010 6010	0.08			8.8	2.4		7.0	
Mickel, Ni	07/05/88	20	2000 100	7740	0,00							3/13
Selenium, 5e	07/05/88	1	500	6010	0.02		ND	ND	0.4	0.3	ND	ND
Silver, Ag	07/01/88	7	700	6010	0.02						3775	ND
Thallium, Ti	07/05/88	24	2400	6010	0.04		ND	ND	ND	ND	ND	ND
Vanadium, V	07/05/88	24 250	5000	6010								
Zinc, Zn	07/05/88	250		<b>J</b> 020								

ND = none detected TR = trace, below detection limit

<sup>3.48</sup>G2.ARS-524

# ANALYTICAL RESULTS SIMMARY CAM Title 22 Metals AA and ICP Analyses

**37.5** 

Client Name: BCL Associates, Inc. Client Job Number: 88-524 Project Name: McLachlan	Lab Receiving No.: 00307 Date Collected: 06/28/88 Date Received (in lab): 06/28/88
Sample Matrix:	Extraction (soils only): STLC
Water (milligrams per liter)	
Soil (milligrams per kilogram)	
V Other (angriev) CAC WET Extract	

Elements	Date Analyzed STLC TILC	Threshold Level STLC (mg/L)	Threshold Level TILC (mg/Kg)	Method	SILC Detection Limit (mg/L)	TTLC Detection Limit (mg/Kg)	BCL #25 38-00307 007 (mg/L)	BCL #28 38-00307 008 (mg/L)	BCL #31 38-00307 009 (mg/L)	BCL #34 38-00307 010 (mg/L)	BCL #37 38-00307 011 (mg/L)	38-00307 012 (mg/L)
				40.0								
ntimony, Sb	07/05/88	1.5	500	6010	0.03							0.16
rsenic, As	07/05/88	5	500	7060	0.03		E 2	5.2			5.3	
arium, Ba	07/05/88	100	10000	6010	0.02		5.3	٥.2		0.05	363	
eryllium, Be	07/05/88	0.75	75	6010	0.02	•				0.05		
admium, Cd	07/05/88	1	100	6010								
hromium, Cr	07/05/88	51	2500	6010								
obalt, Co	07/05/88	80	8000	6010						2.5		
opper, Cu	07/05/88	25	2500	6010	0.01			<b></b>	TR	1.1	TR	1,7
ead, Pb	07/05/88	5	1000	6010	0.2		TR	TR	TK	1.1	IK	2,,,
ercury, Hg	07/05/88	0.2	20	7471								
olybdenum, Mo	07/05/88	250	3500	6010			0 51			12		
lickel, Ni	07/05/88	20	2000	6010	0.08		0.51			12		
elenium, Se	07/05/88	1	100	7740				• • • • • • • • • • • • • • • • • • • •	NES	ND	ND	ND
ilver, Ag	07/01/88	5	500	6010	0.2		0.2	ND	ND	ND	ND	145
hallium, Tl	07/05/88	7	700	6010					1775	MD	NTO	ND
'anadium, V	07/05/88	24	2400	6010	0.04		ИD	ИD	ND	ND	ND	IW
inc, Zn	07/05/88	250	5000	6010								

D = none detected

R = trace, below detection limit

<sup>1.48</sup>G2.ARS-524.1

#### APPENDIX D

California Site Mitigation Decision Tree Manual: RSCL'S

VIII: California, Soil

#### VIII-1

REFERENCE: Recommended Soil Cleanup Levels (RSCLs), Toxic Substances Control Division, California Department of Health Services.

AGENCY: California Department of Health Services.

APPLICATION: Acceptable limit of contaminant in soil.

ENFORCEABILITY: Recommended levels, not regulatory.

SCOPE: Contaminated sites; recommended levels are site specific for organic and inorganic chemicals. Approximately 50 sites were cleaned up between July 1, 1982 and June 30, 1984.

RATIONALE: RSCLs have been established on a site specific basis, with consideration for such factors as chemicals present, extent of contamination, hydrogeological factors, meteorology, and other factors. RSCLs have been based on: (1) drinking water criteria, such as Sanitary Engineering Branch action levels, adjusted for soil attenuation or exposure factors; (2) proposed regulatory criteria for the identification of hazardous waste (California Assessment Manual (CAM) TTLCs); or (3) background concentrations for particular contaminants.

REFERENCE: RSCLs, Epidemiological Studies Section, California Department of Health Services.

AGENCY: California Department of Health Services.

À

APPLICATION: Acceptable limit of contaminant in soil.

ENFORCEABILITY: Recommended level, not regulatory.

SCOPE: Contaminated sites; recommended levels are site specific for organic and inorganic chemicals.

RATIONALE: Derivation of RSCLs have been based on methodology used to develop TTLCs for hazardous waste identification criteria.

$$RSCL = DWS \times 100 \times 10$$

Where RSCL = recommended soil cleanup level;

DWS = drinking water standard;

100 = attenuation of contaminant by soil;

10 = dilution of contaminant by groundwater.

A lifetime risk of  $10^{-6}$  is used for carcinogens.

Additivity is assumed to predict the health effects of mixtures of contaminants. In the absence of available data, the following equation is used for mixtures:

$$\frac{C_1}{RSCL_1} + \frac{C_2}{RSCL_2} + \dots + \frac{C_n}{RSCL_n} = 1$$

where  $C_1$ ,  $C_2$ ... $C_n$  = concentration of each specific contaminant 1, 2,...n in soils.

 $RSCL_1$ ,  $RSCL_2$ ,... $RSCL_n$  = recommended soil cleanup level for contaminants 1, 2,...n.

The derivation of RSCLs is dependent upon the data available on each compound at the contaminated site.

## Sample #19

Methylenc Chloride

$$\frac{C_1}{RSCL_1} + \frac{C_2}{RSCL_2} + \dots + \frac{C_n}{RSCL_n} = 1$$

RSCL, = 40.100.10 = 40,000

$$\frac{C_1}{RSCL_1} = \frac{70}{40,000} = 0.00175$$

Tetrachloroethere

$$RSCL_2 = 4.100.10 = 4000$$

$$\frac{C_2}{RSCL_2} = \frac{7}{4000} = \frac{0.00175}{}$$

III. - Taichloroethane

## 1,2 Dichloroethane

$$\frac{C_4}{RSCL_4} = \frac{0.5}{1000} = \frac{0.0005}{1000}$$

Carbon Tetrachloride

## Bromodichloromethane

Benzenc

$$Concentration = 2$$
 $DWS = 0.7$ 
 $RSCL_{g} = 0.7 \cdot 100 \cdot 10 = 700$ 

$$\frac{C_7}{RSCL_7} = \frac{2}{700} = \frac{0.00286}{100}$$

Methylene Chloride

$$\frac{C_1}{RSCL_1} = \frac{280}{40,000} = \frac{0.007}{1000}$$

Tetra chloroethene

4

$$\frac{C_2}{RSCL_2} = \frac{31}{4000} = \frac{0.00775}{1000}$$

Additive Concentration = 
$$0.007 + 0.00775 = 0.01475$$
  
 $0.01475 < 1$ 

Methylera Chlorida

$$\frac{C_1}{RSCL_1} = \frac{86}{40,000} = 0.00215$$

TETRACHIORGETHENE

$$RSCL_2 = 4000$$

$$\frac{C_2}{RSCL_2} = \frac{27}{4000} = 0.00675$$

1,1,1, - Trichloroethone

$$\frac{C_3}{RSCL_2} = \frac{5}{200,000} = 0.000025$$

Z
$\triangleright$
>
Z
$\infty$
83C
4
042

MIC000131

८६६म् । ३					Boring'	B-1:	B-2	B-3	B-4	<u> 3-5</u>	<b>B-7</b>	B-8	B-9	B-10	B-11	B-12	B-14
Compound	SYLC	111G	0ral 10.50	Dormal 10.50	Sample Peak Con.		4	7	10	16	22	25	2.8	31	34	37.	43
Mit Emony :	5	500	HL.	HL	day at 1.	ND 20.6	40.b.	40'0 ND	40.G	ND 20.6	20.6	ND 20.6	40.6	20.6	40.6	120 40.6	40.6
Arsenia	5.0	500	HL]	HL		2.7	1.9	4.6	63	18.3	2.9	40	2.7	4.7	2.5	3.0	1
86 r lum	100	10000	HL	HL		64	93	53	56	88	70	nd.	104	92	53	102	83
Beryi ( lua	0.75	75	HL	HL	1	0.25	0.42	0.32	0.35	0.39	0.35	0.47	0.48	0.43	1.2	0.47	0.40
· Cad≔ium -	1.0	100	225	, HL		0.47	0.56		46.1		***	0.57			1401	0.31	0.87
Chromium, total	560	2300	NL	HL		14	21	45	16	22	20	36	27	24	29	27	79
Chromium, hexavalent	5	500	HL	HL		<u> </u>		i		Í	i	İ	Ì	j	}	<u> </u>	<u> </u>
Cobalt	80	8000	1500	NL.		4.3	19	12	5.4	35	5.8	7.4	22	19.2	15	7.2	, 5.5
Copper	25	2500	ЯL	HL		6.1	16	42	9.2	23	8.1	14	13	111	59		112
Lwad	5.0	1000	80	HL		2.6	3.2	8.	27	24	2.5	8.7	7.0	10.7	33.3	la J	ALL
Marcury	0.2	20	NL	NL.	]	ND Po.oa	1009	40.09	40.09	TAB	40.09	40.03	40.6	106	NO.6	140.6	-66
∞ No lybdenum	350	3500	NL.	NL		1.6	2.5	4.6	1.3	2.60	1.9	3.3	2.4	2.2	2.1	2.7	25
HI cke1	20	2000	2.5	NL		12	320	150	11	120	13	22	18	15	720	<u></u>	15
.Se Fem Low	1.0	100	6700	NŁ		ND 40.6	40.6	10.7	ND	40.b	40.6	40.6	100	ND	120	130	730
SIlver	5	500	HL	HL	<u> </u>	9.4	4	9.9	75		413	16			170		100
Tha # I funa	7.0	700	HL	HL		ND	40.6	40.6	×0.6	40.6	20.6	40	NO 20	ND	40 G	NO.	A 0. 6
Ýahad I us	24	2400	10	NL	1 . 1	38	53		44	150	BURE TOUR	خير يومه ب		1507		200	-
Zinc	250	5000	ĦL	HL	<u> </u>	24		69	43	68	44	60	59	54	160	i	160

ML - not listed

MA - not applicable

ND - none detected

[All units shown in parts per mittion (ppm)]

15.38.FOR4-3

(refer to CAC Title 22, Division 4, Chapter 30, Article 11, Section 66700(b))

## **BCL**

# Lecter of Transmittal

Integrated Specialties
lo
No. 88-524  I by MessengerYour Pick-up
Sheet No.
tion
✓Information
il



#### BCL ASSOCIATES, INC.

Planners • Engineers • Scientists • Chemists



5702 Bolsa Avenue, Huntington Beach, CA 92649 / (714) 892-2565 (213) 437-4148

January 13, 1988

Mr. Gene Hoggatt McLachlan Investment Company 1400 Dove Street Newport Beach, CA 92660

RE:

BCLA Project No. 88-524

RECEIVED

JAN 15 1988

WELACKLING WAS STREET NEWFORK BEACH, GA

Dear Mr. Hoggatt:

In accordance with your January 12, 1988 telephone conversation we have begun work on the Integrated Specialties, Inc. site. As we discussed, our work will consist of the following:

#### Industrial Wastewater Clarifiers

Previous information suggested that there are five industrial wastewater clarifiers on-site. BCLA will drill one corehole through the concrete near each of the five clarifiers. A hand auger will then be used to collect soil samples from the cored locations at 0, 12, and 24 inches below the bottom of the concrete pad. Soil samples are to be placed in two 40 ml glass VOA vials and one 8 ounce glass jar. The jars will be labeled, sealed, stored in an insulated chest with dry ice, and delivered to the laboratory.

Bermed Concrete Pads Inside of the East Wall and Bermed Concrete Pad for Storage Tanks Outside of the East Wall

BCLA will use the techniques discussed above to collect soil samples from three core holes drilled through the inside pad and three core holes drilled through the outside pad.

#### 1,1,1-Trichloroethane Tanks

Mr. Don Farmer of Integrated Specialties, Inc. indicated to BCLA that the building had two 1,1,1-Trichloroethane tanks. One tank was located at the morth end and one near the center of the building. BCLA will use the same techniques as discussed in the clarifier program to collect soil samples from a core hole drilled below each of the two tanks.

#### Cooling Water Sump

The techniques described in the section on clarifiers is to be used to collect samples from one core hole drilled through the cooling water sump.

#### Electrical Transformer Pad

BCLA was informed that the on-site electrical transformers have been removed from the property. There is a potential that the transformers contained PCB fluids. Such fluid could have leaked causing soil contamination. To investigate this possibility, BCLA will pour tap water on the pad at the locations where the transformers were mounted. Sufficient water will be applied such that the water runs off the pad. The points at which the water contacts soil will be assumed to be the most likely locations for PCB fluids to have contacted soil. A surface soil sample will be collected from the two points which are indicated by the water test to be the most likely contamination areas. The soil from each of these two locations will be collected in separate 8 ounce glass jars. The jars will be processed as discussed in the clarifier section.

A portion of each of the samples are to be scanned in the field for pore space gas with a portable flame ionization detector (FID) and photo ionization detector (PID) using the headspace method. The samples are also to be analyzed in the field with a portable infrared analyzer (IR) using a modified EPA method 418.1.

The soil samples are to be analyzed by a chemcial laboratory based on the following schedule:

Number of Samples to be Analyzed from Each Area

	Clarifiers	Bermed Pads	1,1,1 Tanks	Water Pad	Transformer Pad	Total Analyses
State 17 TTLC Metals	5	6 n	0	1 0	0 0	12 4
8240 VOA's 8080 PCB's	0	ő	0	ŏ	2	2
pH Total Saw Cuts	5 5	6 6	0 2	<b>0</b> 1	0	11

For the State 17 TTLC Metals and pH, the samples collected from below the concrete will be analyzed. For the 8240 runs, the two samples from the 1,1,1-Trichloroethane tank areas exhibiting the highest headspace results will be analyzed. Both of the samples collected from the transformer pad are to be analyzed for PCB.

As we discussed McLachlan will be responsible for re-concreting the 14 saw cuts.



Mr. Gene Hoggatt January 13, 1988 Page Three

Following receipt of the laboratory results, BCLA will prepare a report which summarizes the field investigations, discusses the analytical results and provides an opinion regarding the potential for on-site soil contamination.

To formalize our relationship please sign both copies of the enclosed contract and return one to us along with the specified retainer.

incerely,//

James J Severns

JJS:cli 4.12F.HOGGATT2

Enclosure





5702 Bolsa Avenue, Huntington Beach, CA 92649

BCL A	ASSOCIATES, INC.		CLIENT NO:	88-524							
	EREBY AUTHORIZED TO		DATE:	1-12-88							
	NEERING AND/OR PLAI RE PROPERTY LOCATEI		TAKEN BY:	JJ\$							
ON II	RE PROPERIT LOCATED	n wr:									
	ET ADDRESS:		ntegrated Specialties, Inc.								
LEGA	L DESCRIPTION:	1551 East Orangethorpe Fullerton, CA									
		fullerton, CA									
SERV	ICES REQUESTED:	Subsurface investigation in accordance with BCLA's									
		January 12, 1988 1e	tter.	•							
CHAR	GES SHALL BE BASED	ON:									
(A)	IN THE EVENT OF A	NY INCREASE OF COSTS	DUE TO THE GRANTING	G OF WAGE INCREASES AND/							
				ABOR AGREEMENT DURING							
		HIS AGREEMENT, SUCH		DJUSTED TO ALL FEES. REQUEST. AFTER AGREEMENT							
				ACT PRICE. PREVAILING							
	HOURLY RATES FOR	FIELD AND OFFICE TIM	E ARE AS SHOWN ON T	HE ATTACHED FEE SCHEDULE.							
	המינים או האולים או	ORIZED BY OWNER SHAL	ד סמי סדונים איז יידעם איז איני	AND ONE-UATE							
	Overtime, if Ading	DRIED DI OWNER SHRL	P DE BITTER WI IILE	AND ONE-RALF.							
(B)		UNICIPAL AGENCIES WI									
	EXPENSES WILL BE	AN ADDITIONAL CHARGE	, UNLESS OTHERWISE	NOTED BELOW.							
(C)	ESTIMATE:	\$15,400									
(5)											
(D)	OTHER:										
(E)	RETAINER:	\$ 4,000									
F)	THE ACCOMPANYING I	PAGES OF THIS CONTRA	OT STAIL RE CONSTITU	ማስቹዋችዊ ጥርልዊ ል ሰቹዋ							
£ )	IND ACCOUNTING	rades of this contra	CI SHREE DE CORSIDE.	AED A TART THEREOF.							
(G)				on 3097 of the California							
				e acknowledgement of							
				, services, equipment or stimated of the total							
				hed. If bills are not							
	paid in full for t	the labor / equipment		furnished, the property							
	may be subject to	mechanics liens.									
SIGNE	ED BY: James /	Severis	SIGNED BY:								
		verns, Principal Sci									
FOR:	BCE ASSOCIATES, I	INC	FOR:								
DATE:			DATE:								
<b></b> •											
Fees	for services rende	ered become due and	payable upon comple	tion of work or as work							

progresses, and will be invoiced monthly; terms are net 30 days. Overdue accounts

will incur a finance charge of 11/2 percent per month.